

Vehicle Inspection Report



Regular Inspection

Inspection Details

Report #: GRAB1736580308
Inspection Date: 11-Jan-2025 12:55 PM
Location: JAKARTA
Inspector Denso 01

Vehicle Details



License Number : B 1869 PDC
Engine Number : TZ200XSAN 4D4053681
Model : BYD M6 Standard
Make : BYD
Meter Reading : 0 KM
Vehicle Status: **Maintenance Required**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		✓	○	○	○
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		○	✗	○	○
3	Indicator Dashboard termasuk kelengkapannya		✓	○	○	○
4	Central Lock dan Power Window		✓	○	○	○
5	Fungsi Jok dan Sabuk Pengaman		○	✗	○	○
6	Kelengkapan Karpet dasar, karpet tambahan		✓	○	○	○
7	Radio Tape dan Fungsinya		✓	○	○	○
8	Ban Kanan termasuk Velg dan baut atau mur roda		✓	○	○	○
9	Fender Kanan		✓	○	○	○
10	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		✓	○	○	○
11	Kaca Depan	hello hello	○	✗	○	○
12	Kap Mesin		○	○	✗	○
13	Grill (termasuk emblem)		○	○	✗	○
14	Bumper Depan		○	○	✗	○
15	Lampu depan (Kanan dan Kiri)		○	○	✗	○
16	Fog Lamp & Cover (Kanan dan Kiri)		○	○	✗	○
17	Lampu Sign (Kanan dan Kiri)		✓	○	○	○
18	Oli mesin dan Kebocoran Oli		✓	○	○	○

19	Radiator dan Kebocoran air		☒	☐	☐	☐
20	Battery (Aki) termasuk bracket dan terminal aki		☒	☐	☐	☐
21	Fungsi Starter		☒	☐	☐	☐
22	Fungsi Alternator		☒	☐	☐	☐
23	Fungsi Kompresor		☒	☐	☐	☐
24	Fender Kiri		☒	☐	☐	☐
25	Ban Kiri termasuk Velg dan baut atau mur roda		☐	☒	☐	☐
26	Pintu Kiri		☐	☒	☐	☐
27	Pintu Penumpang Kiri		☒	☐	☐	☐
28	Dongkrak , Tuas Dongkrak,		☒	☐	☐	☐
29	Segitiga Pengaman,		☒	☐	☐	☐
30	Kotak P3K		☒	☐	☐	☐
31	Apar		☒	☐	☐	☐
32	Quarter Panel Kiri		☒	☐	☐	☐
33	Ban Belakang Kiri termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
34	Barcode Pertamina		☒	☐	☐	☐
35	Pintu Belakang termasuk Emblem		☐	☒	☐	☐
36	Bumper Belakang		☐	☐	☒	☐
37	Kaca Pintu Belakang		☐	☐	☒	☐
38	Lampu Stop Kanan dan Kiri		☐	☐	☒	☐
39	Ban Serep termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
40	Quarter Panel Kanan		☒	☐	☐	☐
41	Pintu Penumpang Kanan		☒	☐	☐	☐
42	Atap		☒	☐	☐	☐
43	Ban Belakang Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
44	STNK		☐	☒	☐	☐
45	ID Card Driver		☐	☐	☒	☐
46	Lainnya		☐	☐	☒	☐

11. Kaca Depan



11:56 ...31.6KB/s

< Inspection

Search

HV11028

Inspector: Liam 4 Fault

Vehicle: SF-5609 XD - DOZAR

Corrective Action: Not taken

Date: 20-Aug-2022 11:39 AM

HV11027

Inspector: JOHN 1 Fault

Vehicle: WL00204843 - WHEEL LOADER (JCB455X)

Corrective Action: Taken W01032

Date: 19-Aug-2022 02:37 PM

HV11026

Inspector: JOHN 2 Fault

Vehicle: X542-AT040S015 - BACKHOE LOADER (3DX PLUS)

Corrective Action: Taken

Date: 19-Aug-2022 02:37 PM

+ Start New Inspection

Additional Note

To connect with asset to any

Overall Condition:

A little wear

Vehicle Safe to Use:

No, Unsafe condition Do not Operate

Maintenance Priority:

High

A handwritten signature in black ink, consisting of stylized, overlapping loops and lines.

Inspector Signature