

Vehicle Inspection Report



REGULAR INSPECTION ICE

Inspection Details

Report #: GRAB1738650311
Inspection Date: 04-Feb-2025 01:25 PM
Location: JAKARTA
Inspector : rifkysulistian

Vehicle Details

License Number : B 2987 BZR
Engine Number : 3NRH243548
Model : SIGRA R MT STD 1.2
Make : DAIHATSU
Odometer: 100 KM
Vehicle Status: Available

A. KABIN KANAN DEPAN

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☒	☐	☐	☐
4	Central Lock dan Power Window		☒	☐	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☒	☐	☐	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☒	☐	☐	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐
8	Fungsi Kamera 360 & Tampilan (EV)		☒	☐	☐	☐
9	Tire Pressure Monitoring System (EV)		☒	☐	☐	☐

B. LUAR KANAN DEPAN BAWAH

SN	Inspection Item	Note	Good	Repair	Replace	NA
10	Ban Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐

C. LUAR KANAN DEPAN ATAS

SN	Inspection Item	Note	Good	Repair	Replace	NA
11	Fender Kanan		☒	☐	☐	☐
12	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		☒	☐	☐	☐

D. RUANG MESIN DAN KACA

SN	Inspection Item	Note	Good	Repair	Replace	NA
----	-----------------	------	------	--------	---------	----

13	Kaca Depan		☒	☐	☐	☐
14	Kap Mesin		☒	☐	☐	☐
15	Grill (termasuk emblem)		☒	☐	☐	☐
16	Bumper Depan		☒	☐	☐	☐
17	Lampu depan (Kanan dan Kiri)		☒	☐	☐	☐
18	Fog Lamp & Cover (Kanan dan Kiri)		☒	☐	☐	☐
19	Lampu Sign (Kanan dan Kiri)		☒	☐	☐	☐
20	Oli mesin dan Kebocoran Oli		☒	☐	☐	☐
21	Radiator dan Kebocoran air		☒	☐	☐	☐
22	Battery (Aki) termasuk bracket dan terminal aki		☒	☐	☐	☐
23	Fungsi Starter		☒	☐	☐	☐
24	Fungsi Alternator		☒	☐	☐	☐
25	Fungsi Kompresor		☒	☐	☐	☐

E. LUAR KIRI DEPAN BAWAH

SN	Inspection Item	Note	Good	Repair	Replace	NA
26	Fender Kiri		☒	☐	☐	☐
27	Ban Kiri termasuk Velg dan baut atau mur roda		☒	☐	☐	☐

F. LUAR KIRI DEPAN ATAS

SN	Inspection Item	Note	Good	Repair	Replace	NA
28	Pintu Kiri		☒	☐	☐	☐
29	Pintu Penumpang Kiri		☒	☐	☐	☐

G. BAGASI BELAKANG

SN	Inspection Item	Note	Good	Repair	Replace	NA
30	Dongkrak , Tuas Dongkrak,		☒	☐	☐	☐
31	Segitiga Pengaman,		☒	☐	☐	☐
32	Kotak P3K		☒	☐	☐	☐
33	Apar		☒	☐	☐	☐
34	Tire Repair Kit (EV)		☒	☐	☐	☐

H. LUAR KIRI BELAKANG BAWAH

SN	Inspection Item	Note	Good	Repair	Replace	NA
----	-----------------	------	------	--------	---------	----

35	Quarter Panel Kiri		☒	☐	☐	☐
36	Ban Belakang Kiri termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
37	Barcode Pertamina		☒	☐	☐	☐
38	Kaca Pintu Belakang		☒	☐	☐	☐
39	Lampu Stop Kanan dan Kiri		☒	☐	☐	☐
40	Ban Serep termasuk Velg dan baut atau mur roda		☒	☐	☐	☐

I. LUAR KANAN BELAKANG BAWAH

SN	Inspection Item	Note	Good	Repair	Replace	NA
41	Pintu Belakang termasuk Emblem		☒	☐	☐	☐
42	Bumper Belakang		☒	☐	☐	☐

J. LUAR KANAN BELAKANG ATAS

SN	Inspection Item	Note	Good	Repair	Replace	NA
43	Quarter Panel Kanan		☒	☐	☐	☐
44	Pintu Penumpang Kanan		☒	☐	☐	☐
45	Atap		☒	☐	☐	☐
46	Ban Belakang Kanan termasuk Velg dan baut atau mur roda		☐	☐	☒	☐

46. Ban Belakang Kanan termasuk Velg dan baut atau mur roda



K. DOKUMEN DAN TAMBAHAN

SN	Inspection Item	Note	Good	Repair	Replace	NA
47	STNK		☒	☐	☐	☐

48	ID Card Driver		☒	☐	☐	☐
----	----------------	--	----------------------------------	-----------------------	-----------------------	-----------------------

Additional Note

Overall Condition: Good Condition

Vehicle Safe to Use: **Yes**



Inspector Signature