

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1736767078
Inspection Date: 13-Jan-2025 04:48 PM
Location: BANDUNG
Inspector : Sachin



Vehicle Details

License Number : B 1006 UIQ
Engine Number : 1NRF197511
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 0 KM
Vehicle Status: **Maintenance Required**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☐	☒	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☐	☐	☒	☐
4	Central Lock dan Power Window		☐	☒	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☒	☐	☐	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☒	☐	☐	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐
8	Ban Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
9	Fender Kanan		☒	☐	☐	☐
10	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		☒	☐	☐	☐
11	Kaca Depan		☒	☐	☐	☐
12	Kap Mesin		☒	☐	☐	☐
13	Grill (termasuk emblem)		☒	☐	☐	☐
14	Bumper Depan		☒	☐	☐	☐

3. Indicator Dashboard termasuk kelengkapannya



HVI APP! Finally there is an app to conduct vehicle/
equipment inspections, create work orders, schedule
maintenance/inspections, and more! recurring
basis without having to drag your laptop and camera or
make sticky notes for schedule. Instantly make vehicle
inspections with any mobile device.

[Privacy Policy](#)
[End User License Agreement](#)

www.heavyvehicleinspection.com
Copyright © heavyvehicleinspection.com

Additional Note

G

Overall Condition:

Minor Repair required

Vehicle Safe to Use:

Yes

Maintenance Priority:

High

Inspector Signature