

Vehicle Inspection Report



Regular Inspection

Inspection Details

Report #: GRAB1736576663
Inspection Date: 11-Jan-2025 11:54 AM
Location: JAKARTA
Inspector Denso 01


Vehicle Details

License Number : B 1574 PDK
Engine Number : TZ200XSAN 4D4053713
Model : BYD M6 Standard
Meter Reading: 0 KM
Make BYD
Vehicle Status: Available

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan	Gg this is testing	☐	☒	☐	☐

1. Pintu Kanan



Additional Note

Overall Condition:

A little wear

Vehicle Safe to Use:

Yes

A handwritten signature in black ink, consisting of a series of loops and curves.

Inspector Signature