

Vehicle Inspection Report



OTR Inspection 4W

Inspection Details

Report #: GRAB1736588845
Inspection Date: 11-Jan-2025 03:17 PM
Location: JAKARTA
Inspector Denso 01

Vehicle Details

License Number : B 1166 PDL
Engine Number : TZ200XSAN 4D4038777
Model : BYD M6 Standard
Make : BYD
Meter Reading: : 02500 KM
Vehicle Status: Available

Bagasi Belakang

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Dongkrak , Tuas Dongkrak,		☒	☐	☐	☐
2	Segitiga Pengaman,		☒	☐	☐	☐

Additional Note

Overall Condition: Excellent Condition
Vehicle Safe to Use: Yes

Inspector Signature