

Vehicle Inspection Report



OTR Inspection 4W

Inspection Details

Report #: GRAB1736752117
Inspection Date: 13-Jan-2025 12:38 PM
Location: JAKARTA
Inspector : Denso 01

Vehicle Details

License Number : B 2857 UFD
Engine Number : 1NRF255073
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 25 KM
Vehicle Status: **Maintenance Required**

Bagasi Belakang

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Dongkrak , Tuas Dongkrak,		☒	☐	☐	☐
2	Segitiga Pengaman,	hello hello hello	☐	☒	☐	☐
3	Kotak P3K		☐	☐	☒	☐
4	Apar		☒	☐	☐	☐
5	Tire Repair Kit (EV)		☐	☐	☒	☐

2. Segitiga Pengaman,

Q Search

B01LZ8RP40

Tool Name Dewatering Pump

Quantity 21

Manufacture Trupow

B07L5K55PV

Tool Name Cordless Drill

Quantity 18

Manufacture TECCPO Power

B08TLWSQFQ

Tool Name Surface Vibrator

Quantity 64

Manufacture AlphaWorks

B21092

Tool Name Wheel Barrow


Quantity 49

Manufacture BASS HARDWARE

F1290

Tool Name Wooden Float/wooden Rendering Float

Quantity 150



Additional Note

Overall Condition:	Minor Repair required
Vehicle Safe to Use:	Yes
Maintenance Priority:	Low



Inspector Signature