

Vehicle Inspection Report



Regular Inspection

Inspection Details

Report #: GRAB1737366425
Inspection Date: 20-Jan-2025 04:48 PM
Location: JAKARTA
Inspector : CIPONDOH 100251 TUNAS TOYOTA

Vehicle Details


License Number : B 1871 PDC
Engine Number : TZ200XSAN 4D4040182
Model : BYD M6 Standard
Make : BYD
Odometer: 45000 KM
Vehicle Status: **Maintenance Required**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☐	☒	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☒	☐	☐	☐
4	Central Lock dan Power Window		☒	☐	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☒	☐	☐	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☒	☐	☐	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐
8	Ban Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
9	Fender Kanan		☒	☐	☐	☐
10	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		☒	☐	☐	☐
11	Kaca Depan		☒	☐	☐	☐
12	Kap Mesin		☒	☐	☐	☐
13	Grill (termasuk emblem)		☒	☐	☐	☐
14	Bumper Depan		☒	☐	☐	☐
15	Lampu depan (Kanan dan Kiri)		☒	☐	☐	☐
16	Fog Lamp & Cover (Kanan dan Kiri)		☒	☐	☐	☐
17	Lampu Sign (Kanan dan Kiri)		☒	☐	☐	☐
18	Oli mesin dan Kebocoran Oli		☒	☐	☐	☐

19	Radiator dan Kebocoran air		☒	☐	☐	☐
20	Battery (Aki) termasuk bracket dan terminal aki		☒	☐	☐	☐
21	Fungsi Starter		☒	☐	☐	☐
22	Fungsi Alternator		☒	☐	☐	☐
23	Fungsi Kompresor		☒	☐	☐	☐
24	Fender Kiri		☒	☐	☐	☐
25	Ban Kiri termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
26	Pintu Kiri		☒	☐	☐	☐
27	Pintu Penumpang Kiri		☒	☐	☐	☐
28	Dongkrak , Tuas Dongkrak,		☒	☐	☐	☐
29	Segitiga Pengaman,		☒	☐	☐	☐
30	Kotak P3K		☒	☐	☐	☐
31	Apar		☒	☐	☐	☐
32	Quarter Panel Kiri		☒	☐	☐	☐
33	Ban Belakang Kiri termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
34	Barcode Pertamina		☒	☐	☐	☐
35	Pintu Belakang termasuk Emblem		☒	☐	☐	☐
36	Bumper Belakang		☒	☐	☐	☐
37	Kaca Pintu Belakang		☒	☐	☐	☐
38	Lampu Stop Kanan dan Kiri		☒	☐	☐	☐
39	Ban Serep termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
40	Quarter Panel Kanan		☒	☐	☐	☐
41	Pintu Penumpang Kanan		☒	☐	☐	☐
42	Atap		☒	☐	☐	☐
43	Ban Belakang Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
44	STNK		☒	☐	☐	☐
45	ID Card Driver		☒	☐	☐	☐
46	Lainnya		☒	☐	☐	☐

1. Pintu Kanan



Additional Note

Pintu sobek

Overall Condition: A little wear
Vehicle Safe to Use: **Yes**
Maintenance Priority: Low

A handwritten signature in black ink, consisting of a stylized 'S' followed by a checkmark-like flourish.

Inspector Signature