

Vehicle Inspection Report



OTR Inspection 4W

Inspection Details

Report #: GRAB1738052067
Inspection Date: 28-Jan-2025 01:44 PM
Location: JAKARTA
Inspector : Denso 01

Vehicle Details

License Number : BK 1798 QL
Engine Number : 3NRH256513
Model : SIGRA R MT STD 1.2
Make : DAIHATSU
Odometer: 0 KM
Vehicle Status: Available

Bagasi Belakang

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Dongkrak , Tuas Dongkrak,		☒	☐	☐	☐
2	Segitiga Pengaman,		☐	☒	☐	☐

Additional Note

Overall Condition: A little wear
Vehicle Safe to Use: Yes

Inspector Signature

INFORMASI UMUM

A. PERAWATAN RUTIN (MAINTENANCE)

	SERVICE RUTIN	BAN DAN AKI
KAPAN	10.000 KM <i>Avanza, Xenia, New Ertiga</i> (dengan nilai toleransi Kilometer +/- 500 Km) 15.000 KM <i>Calya, Sigra, Transmover, Livina</i> (dengan nilai toleransi Kilometer +/- 500 Km)	•Ban kurang dari standar TWI (1 mm) •Kondisi aki di nyatakan tidak layak pakai.
PAKET SERVICE	Service berkala dan pergantian part sesuai ketentuan service	
LOKASI	Bengkel rekanan	Pool TPI di BSD
KUOTA	Sesuai paket service dan Juklak TPI*	Berdasarkan kondisi actual
PIC	62 813-1728-5511 (Heri) 62 838-3079-3110 (Ilyas) 62 815-6789-0812 (Adrian PIC <i>Avanza, Xenia, Ertiga</i>)	62 813-1184-5681 (Dedy) 62 821-1107-7422 (Ginangjar)
KETERANGAN	Wajib datang, jika melewati waktu service (7 hari) dari jadwal akun akan di non aktifkan	

B. CALL CENTER ERA - JIKA MENEMUKAN KENDALA DI JALAN

021-

C. PELAKSANAAN CHECKPOINT SETIAP 14 HARI SEKALI (WAJIB DISIPLIN)



Jika
OR s

H+1 SERAHTERIMA

H+14 PELAKSANAAN

*Kelalaian atas pemenuhan batas waktu yg telah dijadwalkan/ditentukan

PEN

1. ME

2. MENAMBAH ATAU

3. MENGHIDUPKAN KOMP