

# Vehicle Inspection Report



## REGULAR INSPECTION ICE

### Inspection Details

Report #: GRAB1738746504  
Inspection Date: 05-Feb-2025 04:09 PM  
Location: JAKARTA  
Inspector : rifkysulistian



### Vehicle Details

License Number : B 1166 PDL  
Engine Number : TZ200XSAN 4D4038777  
Model : BYD M6 Standard  
Make : BYD  
Odometer: 45000 KM  
Vehicle Status: **Maintenance Required**


#### A. KABIN KANAN DEPAN

| SN | Inspection Item                                        | Note    | Good                             | Repair                           | Replace                          | NA                    |
|----|--------------------------------------------------------|---------|----------------------------------|----------------------------------|----------------------------------|-----------------------|
| 1  | Pintu Kanan                                            | level 3 | <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/> |
| 2  | Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan |         | <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/> |
| 3  | Indicator Dashboard termasuk kelengkapannya            |         | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |
| 4  | Central Lock dan Power Window                          |         | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |
| 5  | Fungsi Jok dan Sabuk Pengaman                          |         | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |
| 6  | Kelengkapan Karpet dasar, karpet tambahan              |         | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |
| 7  | Radio Tape dan Fungsinya                               |         | <input type="radio"/>            | <input type="radio"/>            | <input checked="" type="radio"/> | <input type="radio"/> |
| 8  | Fungsi Kamera 360 & Tampilan (EV)                      |         | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |
| 9  | Tire Pressure Monitoring System (EV)                   |         | <input checked="" type="radio"/> | <input type="radio"/>            | <input type="radio"/>            | <input type="radio"/> |

### 2. Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan



## 7. Radio Tape dan Fungsinya



### B. LUAR KANAN DEPAN BAWAH

| SN | Inspection Item                                | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|------------------------------------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 10 | Ban Kanan termasuk Velg dan baut atau mur roda |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

### C. LUAR KANAN DEPAN ATAS

| SN | Inspection Item                                   | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|---------------------------------------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 11 | Fender Kanan                                      |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12 | Spion (Kanan dan Kiri) termasuk Cover dan Kacanya |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

### D. RUANG MESIN DAN KACA

| SN | Inspection Item | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|-----------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 13 | Kaca Depan      |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

|    |                                                 |  |                                     |                          |                          |                          |
|----|-------------------------------------------------|--|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 14 | Kap Mesin                                       |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15 | Grill (termasuk emblem)                         |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 16 | Bumper Depan                                    |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 17 | Lampu depan (Kanan dan Kiri)                    |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18 | Fog Lamp & Cover (Kanan dan Kiri)               |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 19 | Lampu Sign ( Kanan dan Kiri)                    |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 20 | Oli mesin dan Kebocoran Oli                     |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 21 | Radiator dan Kebocoran air                      |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 22 | Battery (Aki) termasuk bracket dan terminal aki |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 23 | Fungsi Starter                                  |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 24 | Fungsi Alternator                               |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 25 | Fungsi Kompresor                                |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

#### E. LUAR KIRI DEPAN BAWAH

| SN | Inspection Item                               | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|-----------------------------------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 26 | Fender Kiri                                   |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 27 | Ban Kiri termasuk Velg dan baut atau mur roda |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

#### F. LUAR KIRI DEPAN ATAS

| SN | Inspection Item      | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|----------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 28 | Pintu Kiri           |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 29 | Pintu Penumpang Kiri |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

#### G. BAGASI BELAKANG


| SN | Inspection Item           | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|---------------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 30 | Dongkrak , Tuas Dongkrak, |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 31 | Segitiga Pengaman,        |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 32 | Kotak P3K                 |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 33 | Apar                      |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 34 | Tire Repair Kit (EV)      |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

#### H. LUAR KIRI BELAKANG BAWAH

| SN | Inspection Item    | Note | Good                     | Repair                              | Replace                  | NA                       |
|----|--------------------|------|--------------------------|-------------------------------------|--------------------------|--------------------------|
| 35 | Quarter Panel Kiri |      | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

|    |                                                        |  |                                     |                          |                          |                          |
|----|--------------------------------------------------------|--|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 36 | Ban Belakang Kiri termasuk Velg dan baut atau mur roda |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 37 | Barcode Pertamina                                      |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 38 | Kaca Pintu Belakang                                    |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 39 | Lampu Stop Kanan dan Kiri                              |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 40 | Ban Serep termasuk Velg dan baut atau mur roda         |  | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

### 35. Quarter Panel Kiri



#### I. LUAR KANAN BELAKANG BAWAH

| SN | Inspection Item                | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|--------------------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 41 | Pintu Belakang termasuk Emblem |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 42 | Bumper Belakang                |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

#### J. LUAR KANAN BELAKANG ATAS

| SN | Inspection Item                                         | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|---------------------------------------------------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 43 | Quarter Panel Kanan                                     |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 44 | Pintu Penumpang Kanan                                   |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 45 | Atap                                                    |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 46 | Ban Belakang Kanan termasuk Velg dan baut atau mur roda |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

#### K. DOKUMEN DAN TAMBAHAN

| SN | Inspection Item | Note | Good                                | Repair                   | Replace                  | NA                       |
|----|-----------------|------|-------------------------------------|--------------------------|--------------------------|--------------------------|
| 47 | STNK            |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 48 | ID Card Driver  |      | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

| Additional Note |
|-----------------|
| minor           |

|                       |                       |
|-----------------------|-----------------------|
| Overall Condition:    | Minor Repair required |
| Vehicle Safe to Use:  | Yes                   |
| Maintenance Priority: | High                  |



\_\_\_\_\_  
Inspector Signature