

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1737199756
Inspection Date: 18-Jan-2025 04:59 PM
Location: Bali
Inspector : Approver G5

Vehicle Details

License Number : B 1006 UIO
Engine Number : 1NRF182008
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 36 KM
Vehicle Status: **Maintenance Required**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☐	☒	☐	☐
4	Central Lock dan Power Window		☐	☒	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☐	☐	☒	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☐	☐	☒	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐

Additional Note

Overall Condition:

Minor Repair required

Vehicle Safe to Use:

Yes

Maintenance Priority:

Medium



Inspector Signature