

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1737973455
Inspection Date: 27-Jan-2025 03:54 PM
Location: SEMARANG
Inspector : Approver G3


Vehicle Details

License Number : B 1005 UIQ
Engine Number : 1NRF195650
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 02 KM
Vehicle Status: **Breakdown**




BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya	hello hello 123	☐	☒	☐	☐
4	Central Lock dan Power Window		☐	☐	☒	☐
5	Fungsi Jok dan Sabuk Pengaman		☐	☐	☒	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☒	☐	☐	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐
8	Ban Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
9	Fender Kanan		☒	☐	☐	☐
10	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		☒	☐	☐	☐
11	Kaca Depan		☐	☒	☐	☐
12	Kap Mesin		☒	☐	☐	☐
13	Grill (termasuk emblem)		☒	☐	☐	☐
14	Bumper Depan		☒	☐	☐	☐

3. Indicator Dashboard termasuk kelengkapannya



11. Kaca Depan



Additional Note

Overall Condition:	Minor Repair required
Vehicle Safe to Use:	Yes
Maintenance Priority:	High



Inspector Signature