

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1737974430
Inspection Date: 27-Jan-2025 04:10 PM
Location: SEMARANG
Inspector : Approver G3

Vehicle Details

License Number : B 1005 UIQ
Engine Number : 1NRF195650
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 0 KM
Vehicle Status: **Breakdown**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☐	☒	☐	☐
4	Central Lock dan Power Window		☒	☐	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☐	☐	☒	☐

Additional Note

Overall Condition: Minor Repair required
Vehicle Safe to Use: **No, Unsafe condition Do not Operate**
Maintenance Priority: Medium

Inspector Signature