

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1737976720
Inspection Date: 27-Jan-2025 04:48 PM
Location: MAKASSAR
Inspector : Sachin


Vehicle Details

License Number : B 1006 UIQ
Engine Number : 1NRF197511
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 0 KM
Vehicle Status: Available

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan	Test	☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☒	☐	☐	☐
4	Central Lock dan Power Window		☒	☐	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☒	☐	☐	☐

2. Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan





Additional Note

Overall Condition:

Excellent Condition

Vehicle Safe to Use:

Yes

Inspector Signature