

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1738058723
Inspection Date: 28-Jan-2025 03:35 PM
Location: MAKASSAR
Inspector : Sachin

Vehicle Details

License Number : B 1006 UIQ
Engine Number : 1NRF197511
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 0 KM
Vehicle Status: Available

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐

Additional Note

Overall Condition: Excellent Condition
Vehicle Safe to Use: Yes

Inspector Signature