

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1738065694
Inspection Date: 28-Jan-2025 05:31 PM
Location: MAKASSAR
Inspector : Sachin



Vehicle Details

License Number : B 1001 UIQ
Engine Number : 1NRF197422
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 0 KM
Vehicle Status: **Maintenance Required**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☒	☐	☐	☐
4	Central Lock dan Power Window		☒	☐	☐	☐
5	Fungsi Jok dan Sabuk Pengaman	Need to be replaced	☐	☐	☒	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☒	☐	☐	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐
8	Ban Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
9	Fender Kanan		☒	☐	☐	☐
10	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		☒	☐	☐	☐
11	Kaca Depan		☒	☐	☐	☐
12	Kap Mesin		☒	☐	☐	☐
13	Grill (termasuk emblem)		☒	☐	☐	☐
14	Bumper Depan		☒	☐	☐	☐

5. Fungsi Jok dan Sabuk Pengaman



Additional Note

Test Inspection

Overall Condition:

Good Condition

Vehicle Safe to Use:

No, Unsafe condition Do not Operate

Maintenance Priority:

High

5 3 5

Inspector Signature