

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1738219599
Inspection Date: 30-Jan-2025 12:17 PM
Location: SEMARANG
Inspector : Approver G3

Vehicle Details

License Number : B 1006 UIQ
Engine Number : 1NRF197511
Model : AVANZA E MT 1.3
Make : TOYOTA
Odometer: 0 KM
Vehicle Status: **Breakdown**

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☐	☒	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☐	☐	☒	☐
4	Central Lock dan Power Window		☒	☐	☐	☐
5	Fungsi Jok dan Sabuk Pengaman		☒	☐	☐	☐
6	Kelengkapan Karpet dasar, karpet tambahan		☐	☐	☒	☐
7	Radio Tape dan Fungsinya		☒	☐	☐	☐
8	Ban Kanan termasuk Velg dan baut atau mur roda		☒	☐	☐	☐
9	Fender Kanan		☒	☐	☐	☐
10	Spion (Kanan dan Kiri) termasuk Cover dan Kacanya		☒	☐	☐	☐

Additional Note

Overall Condition:

Minor Repair required

Vehicle Safe to Use:

Yes

Maintenance Priority:

Low



Inspector Signature