

Vehicle Inspection Report



General inspection

Inspection Details

Report #: GRAB1738913025
Inspection Date: 07-Feb-2025 12:54 PM
Location: BANDUNG
Inspector : 1234wer

Vehicle Details

License Number : B 1007 UIJ
Engine Number : HYUN912331
Model : IONIQ-6
Make : HYUNDAI
Odometer: 0 KM
Vehicle Status: Available

BODY CONDITION

SN	Inspection Item	Note	Good	Repair	Replace	NA
1	Pintu Kanan		☒	☐	☐	☐
2	Kondisi Seat Cover , Plafon, Kaca film, dan Kebersihan		☒	☐	☐	☐
3	Indicator Dashboard termasuk kelengkapannya		☒	☐	☐	☐

Additional Note

Overall Condition: Excellent Condition
Vehicle Safe to Use: Yes

Inspector Signature